
# **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Run Summa	iry <del></del>						
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-207	Smoke	7/28/2009	ADS/TM	S17AA_002MH	Dry	Yes	663.79



# **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Run Summar	у						_
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-207	Smoke	7/28/2009	ADS/TM	S17AA_002MH	Dry	Yes	663.79

### **Isolated Pipes**

\$17AA_027G1 \$17AA_027MH \$17AA_002MH \$3.1951 8   \$17AA_002G1 \$17AA_002MH \$17AA_037MH 285.154 8   \$17AA_037G1 \$17AA_037MH \$17AA_008MH 295.438 8	Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
	S17AA_027G1	S17AA_027MH	S17AA_002MH	83.1951	8
S17AA 037G1 S17AA 037MH S17AA 008MH 295.438 8	S17AA_002G1	S17AA_002MH	S17AA_037MH	285.154	8
2 2 2 2 2	S17AA_037G1	S17AA_037MH	S17AA_008MH	295.438	8

### **Observations & Photos**

**Obs\_ID** S1028-207-OB01 **Address** 901 Warwick Ave.

**Status** Public

**Source** Sanitary Manhole

**Location** Alley

Nearest MH S17AA\_037MH

**Comments** Smoke from sanitary manhole S17AA\_037MH

in the alley south of 901 Warwick Ave.



**Picture** \S1028-207-OB01-P01.jpg

**Comments** Warwick Ave. & Alley looking

northwest